VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-3730	DATE	December 12, 2023	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	With regards to the program setting of Aftertreatment Control Module (ACM), due to the inappropriate data selection setting, vehicle operation status data upon failure occurrence situation could not be read by generic scan tools. Thus, the vehicles may not comply with the Japan Safety Regulations article 31, Details of Safety Regulations Section 1 Article 41, Attachment 48 Technical Standard for On-Board Diagnostic (OBD) system (Diesel-powered motor heavy vehicles J-OBDII).			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-4S2TDA1	FH	2023	2	
2KG-4S2TEA1 2PG-4S2TEA1		2023	19	
2KG-4S3RTF1		2023	8	
2KG-5S2TDA1		2023	2	
2KG-5S2TEA1		2023	5	
2KG-5S4RTL1		2023	1	
2DG-5S4TBA1		2023	3	
		TOTAL	40	