

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3683	DATE	December 11, 2023
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The affected CCU has been installed with an unapproved reworking by the supplier. It might result in a failure of the Combined Charging Unit over lifetime (for example: charging interruption, no high-voltage readiness when starting up, the high-voltage system switching off while driving, causing the vehicle to coast slowly).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-42DU44	「BMW iX3 M Sport」	2022	1
ZAA-72AW44	「BMW i4 eDrive40」	2022	1
ZAA-12CF89S	「BMW iX xDrive40」	2022	3
ZAA-52EJ89	「BMW i7 xDrive60」	2022	2
		TOTAL	7