VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI 3738	DATE	19.Jan.2024	
MANUFACTURE	SCANIA CV AB			
	(Japanese Importer:TRANSWEB Co. Ltd.)			
DESCRIPTION OF DEFECT	Due to improper programming of the control unit that controls the lights, when the light check function button on the remote-control key is operated, all lights, including the braking and backing lights, are automatically turned on and off sequentially. In addition, when the approach light function button is operated, the direction indicators remain on, violating safety standards.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	LPGRS series Truck	2018	2
		TOTAL	2