## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

Gai−3764	DATE	Feb. 9th 2024	
Harley-Davidson Motor Company			
(Japanese Importer : Harley-Davidson Japan K.K. )			
On certain early production 2023 FLHXSE and FLTRXSE model motorcycles, a lower frame rail			
clamp may not adequately retain the rear brake line, which may allow the line to contact the			
exhaust. Contact between the brake line and the exhaust could, over time, lead to a ho			
brake line and a loss of rear brake fluid.			
	Harley-Davidson Motor Compa (Japanese Importer: Harley On certain early production 2023 clamp may not adequately retain t exhaust. Contact between the bra	Harley-Davidson Motor Company  (Japanese Importer: Harley-Davidson Japan K.K.)  On certain early production 2023 FLHXSE and FLTRXSE model model clamp may not adequately retain the rear brake line, which may allow exhaust. Contact between the brake line and the exhaust could, over	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-FL6	CVO ROAD GLIDE	2023	189
8BL-FL6	CVO STREET GLIDE	2023	143
		TOTAL	332