

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~X~~ Import Vehicles

CAMPAIGN No.	Gai-3781	DATE	2024/3/26
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain GLE (167 platform) vehicles, a 12V ground connection bolting under the driver seat might not meet specifications.</p> <p>In this case, the bolting might loosen over time and the electric resistance of the connection might increase. Due to the high electrical currents that flow through this connection, the temperature on this connection could increase. This might increase the risk of a fire.</p> <p>Additionally, due to a potential deactivation of the ECO start/stop-function resulting from an increase of the electrical resistance, an influence on the exhaust emissions cannot be ruled out.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-167123	GLE400d 4MATIC	2021	4
		2022	1
		TOTAL	5