## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIGN No.	GAI-3775	Date	March 7, 2024	
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)			
DEFECT	On T-Roc vehicles of a limited production period the bolted connections of a drive shaft to the gearbox may not have been correctly carried out. A loose bolted connection usually leads to loss of drive when pulling away.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3BA-A1DPC	T-ROC 1.5/110kW	MY2024	2
7BA-A1DNFF	T-ROC R 2.0/221kW	MY2024	2
		Total	4