

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic／Import Vehicles

CAMPAIGN No.	GAI-3798	DATE	April 18, 2024	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	With regards to the semiconductor of Air Production Modulator (APM), due to the inappropriate evaluation test, semiconductor which is not satisfied with durability and reliability was assembled on APM. Thus, premature deterioration of the semiconductor causes a continuity failure, resulting in the inoperability of the solenoid valve in the parking brake system, the vehicles may not release nor engage the electric parking brake.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2KG-4K2TDA1	FH	2022	2	
2KG-4K2TEA1		2021	5	
2DG-5K4TBA1		2021	4	
		TOTAL	11	