VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3750	DATE	01. April, 2024	
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)			
DESCRIPTION	The defect affects the hands-on-detection of the option "Driving			
OF	Assistant Plus", "Driving Assistant Professional", "Highway Assistant"			
DEFECT	and/or activated "Preparation Driving Assistant Plus".			
	Due to an intermittent electrical contact caused by a manufacturing			
	fault, the system may detect the driver hands on the steering wheel			
	even though they are not. As a result, the hands-off warning or			
	emergency stop, could not be triggered by the system as required.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-12FJ20	「BMW 523i」	2023	11
3CA-22EJ30	「BMW 740d xDrive」	2022 - 2023	270
3AA-22EH30	「BMW 740i」	2022 - 2023	407
ZAA-32FK45	「BMW i5 eDrive40」	2023	4
ZAA-42FK89	「BMW i5 M60 xDrive」	2023	3
ZAA-42EJ49	「BMW i7 eDrive50」	2023	2
ZAA-82EH93	「BMW i7 M70 xDrive」	2023	2
ZAA-52EJ89	「BMW i7 xDrive60」	2022 - 2023	242
		TOTAL	941