VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3805	DATE	2024/5/16	
MANUFACTURE	Mercedes-Benz AG			
	(Japanese Importer : Mercedes-Benz Japan G.K.)			
DESCRIPTION OF DEFECT	On certain GLE vehicles (167 platform) the software of the transmission control unit might not meet specifications. When a downshift operation of the transmission from 7th to 6th gear would not be fully completed during a slight braking maneuver of the vehicle, the engine might stall, if further specific boundary conditions exist in parallel (i.e. aborted shift operation, low transmission oil temperature, simultaneous recuperation by the 48V starter-alternator). In this case, the vehicle would lose its propulsion until it would come to a standstill and the engine would be restarted. In this connection, the risk of a crash might increase. This behavior does not affect the functionality of the vehicle's steering and braking systems.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
5AA-167159	GLE450 4MATIC	2019	642
		2020	428
		2021	174
		2022	44
-167159-		2019	3
		TOTAL	1,291