

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3844	DATE	July 25, 2024
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	For headlight control unit, the light distribution of the dynamic cornering light function operates while the vehicle is reversing with the light distributing type headlight illuminated by auto headlight mode due to inappropriate software. Therefore, the technical requirements of UN ECE-R48 are not fulfilled.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-F8CWWF	Audi S8	2022-2024	96
3AA-F8CXYF	Audi A8 60Tq	2022-2024	41
3AA-F8CXYL	Audi A8L 60Tq	2022-2024	23
3AA-F8CZSF	Audi A8 55Tq	2022-2024	409
3LA-F8CZSF	Audi A8 60e	2023-2024	112
3LA-F8CZSL	Audi A8L 60e	2024	1
ZAA-GEEAS	Audi e-tron	2023	55
ZAA-GEEASB	Audi e-tron 50	2023	2
ZAA-GEEAV	Audi e-tron S	2022-2024	115
ZAA-GEEDE	Audi Q8 e-tron	2024	205
		Total	1,059