

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3839	DATE	July 12, 2024
MANUFACTURE	FCA US LLC (Japanese Importer : Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	The High Voltage (HV) battery of the affected vehicle may fail internally. An internally failed HV battery could lead to a vehicle fire with the ignition on or off. A vehicle fire can result in increased risk of occupant injury and/or injury to persons outside the vehicle, as well as property damage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-JL20L	Wrangler Unlimited	2023	1
		TOTAL	1