

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

Campaign No.	Gai-3861	Date	August 19, 2024
Manufacturer	Liuzhou Wuling Automobile Industry Co., Ltd. (Japanese Importer: ASF Inc.)		
Description of defect	Some front passenger side airbag covers have not been assembled correctly due to improper manufacturing control. When the front passenger side airbag is triggered, depending on the attachment position of the cover, occupant protection may not function adequately when the airbag deploys.		

Type	Commercial Name	Model Year Recalled	Number of Vehicle
-	-	2023	192
		Total	192