

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3848	DATE	August 1, 2024
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	For braking system, the length of front brake hoses is insufficient due to improper design. Therefore, significant tension caused by steering angle may be applied and cracks may occur on the front axle brake hoses while vehicle in use. In the worst case, brake fluid may leak and the warning message appears on the instrument cluster, then the braking performance could be noticeably restricted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-FWEBGE	Audi RS e-tron GT	2022-2024	306
ZAA-FWEBGS	Audi e-tron GT	2022-2024	435
		Total	741