

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-3871	Date	Sep. 24, 2024
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	During a passenger airbag deployment, the airbag may tear as a result of the instrument panel airbag deployment door panel not being sufficiently weakened. A torn airbag may reduce the occupant protection.  Replacing the passenger airbag.		

Type	Commercial name	Model year recalled	Number of vehicles
3BA-DF2XB	E-PACE	2021-2023	312
3CA-DF2NB			247
3LA-DF15TB			4
		2021-2023	563

(JIS A4 size)