

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3889	DATE	Oct. 15th, 2024
MANUFACTURE	McLaren Automotive (Japanese Importer : McLaren Automotive Asia Pte Ltd.)		
DESCRIPTION OF DEFECT	The manual release cable of the bonnet latch may have excessive tension which potentially may cause the latch to open, causing an unexpected opening of the bonnet.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-P22GT	McLaren GT	2020 - 2023	212
		TOTAL	212