

VEHICLE SAFETY/~~POLLUTION~~ RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

| | | | |
|-----------------------|--|------|------------------|
| CAMPAIGN No. | Gai-3905 | DATE | December/19/2024 |
| MANUFACTURER | Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited) | | |
| DESCRIPTION OF DEFECT | Volvo Cars investigations have identified that certain brake pedals on affected vehicles may not have been assembled correctly, specifically the rod connecting the brake pedal to the brake booster may not have been torqued according to specification. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------|-----------------|---------------------|-------------------|
| VOLVO | [S60] | 2020 | 75 |
| | [V60] | 2020 | 2 |
| | [XC60] | 2020 | 19 |
| | [XC90] | 2020 | 18 |
| | | TOTAL | 114 |