

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic／Import Vehicles

CAMPAIGN No.	Gai-3912	DATE	December 10, 2024	
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)			
DESCRIPTION OF DEFECT	With regards to the urea pump unit, due to inappropriate parts management, some of the units were built with diaphragm which does not satisfy required durability and reliability level. Thus, if the vehicle continues operation in this condition, the diaphragm deteriorating, urea may leak internally, which may lead electrical short circuit. As the urea pump functionality is lost, warning lamp in the instrument cluster is activated, after which the NOx emission might exceed standard level.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-4S2TDA1	FH	2024	3	
2PG-4S2TEA1		2024	14	
		TOTAL	17	