

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3933	DATE	January 23, 2025
MANUFACTURE	FCA US LLC (Japanese Importer : Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	The affected vehicles may have been built with a steering column control module (SCCM) with an insufficient weld between an internal flexible flat cable (FFC) and busbar. The SCCM may not allow a deployment signal from the Occupant Restraint Controller to reach the driver airbag module, preventing airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-JL20L	Wrangler Unlimited	2023	415
7BA-JL36L	Wrangler Unlimited	2023	24
7BA-JL36S	Wrangler	2023	8
7BF-JT36	Gladiator	2023	6
7BA-WL20	Grand Cherokee	2023	38
7BA-WL36L	Grand Cherokee L	2023	16
7BA-WL36LA	Grand Cherokee L	2023	37
		TOTAL	544

Affected vehicles to which suspected parts were installed as replacement parts

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-JL20L	Wrangler Unlimited	2022 – 2023	16
3BA-JL36L	Wrangler Unlimited	2021	5
3BA-JL36S	Wrangler	2021	1
ABA-JL36L	Wrangler Unlimited	2019	2
		TOTAL	24