

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3953	Date	February 27, 2025
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to an improper control program in the infotainment system unit, it may reset during a journey or not start upon establishing travel readiness. As a result, the driver information display will have no display will be possible and this can result in loss of speedometer information.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-E2EBJ	ID.4	2022-2023	3,596
		Total	3,596