

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	Gai-3949	DATE	Feb 26, 2025
MANUFACTURE	FOMM (ASIA) Co., Ltd. Japanese Importer FOMM Corporation.		
DESCRIPTION OF DEFECT	The NUT securing the front motor and front wheel hub was not tightened to the specified torque, nor was the anti-loosening caulking applied. Therefore, on January 13, 2025, in Higashikagawa City, Kagawa Prefecture, Japan, a defect occurred in which the right front wheel detached while in motion. No injuries or accidents resulted from this incident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
N/A	FOMM ONE	2023	1
		TOTAL	1