

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3951	DATE	March 12, 2025
MANUFACTURE	FCA US LLC (Japanese Importer : Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	On some vehicles, the under-seat intermediate connection or the rear connection to Integrated Dual Charging Module (IDCM) on your vehicle may not be tightened to the proper torque. This may result in the 12V battery failing to recharge, which can lead to the vehicle shutting down.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-BV13	「Renegade」	2023	55
7LA-BV13	「Renegade」	2023	1
		TOTAL	56