

第 3 号様式（英文リコール概要書）（第 2 関係）

TIRE SAFETY RECALL CAMPAIGN IN JAPAN				
Domestic/Import Tires				
CAMPAIGN No.	SOUGAI-12	DATE	12, March, 2025	
MANUFACTURER	Pirelli Deutschland GmbH			
DESCRIPTION OF DEFECT	Under certain tyre service conditions (e.g., low inflation pressure, heavy load, road conditions, mileage at almost the half of tyre life, etc.), irregular tyre wear may develop, which, over time, may result in breakage of the zero-degree reinforcement. If this condition is not promptly detected, it may lead to potential detachment of parts of the tread layer and/or sudden air loss.			
COMMERCIAL NAME	TYPE	CLASSIFICATION	MODEL YEAR RECALLED	NUMBER OF ITEMS
Metzeler Metzeler Pirelli	Tourance next Tourance next2 Scorpion trail II	150/70R18 M/C 70V	(1)EB 0M X033 - from 4816 to 2424 (1)EB 0M 614L - from 3521 to 2624 (1)EB 2M X032 - from 0117 to 4024	139 193 189
			TOTAL	521

（日本産業規格 A 列 4 番）