## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3968	DATE	Apr. 16th 2025		
MANUFACTURE	Harley-Davidson Motor Company				
	(Japanese Importer : Harley-Davidson Japan K.K. )				
DESCRIPTION OF DEFECT	On certain early production 2023 FLHXSE and FLTRXSE model motorcycles, a lower frame rail clamp may not adequately retain the rear brake line, which may allow the line to contact the exhaust. Contact between the brake line and the exhaust could, over time, lead to a hole in the brake line and a loss of rear brake fluid.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-FL8	CVO ROAD GLIDE ST	2024	11
8BL-FL7	ROAD GLIDE	2024	9
8BL-FL7	STREET GLIDE	2024	5
8BL-FL6	CVO ROAD GLIDE	2023	3
8BL-FL6	CVO STREET GLIDE	2023	1
		TOTAL	29