

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3999	DATE	19. May, 2025
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>The defect affects the hands-on-detection of the option “Driving Assistant Plus”, “Driving Assistant Professional”, “Highway Assistant” and/or activated “Preparation Driving Assistant Plus”.</p> <p>Due to an intermittent electrical contact caused by a manufacturing fault, the system may detect the driver hands on the steering wheel even though they are not. As a result, the hands-off warning or emergency stop, could not be triggered by the system as required.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-22FL20	BMW 520d xDrive	2024	85
3CA-22GW20	BMW 523d xDrive Touring	2024	19
3AA-12FJ20	BMW 523i	2024	81
3CA-22EJ30	BMW 740d xDrive	2024	7
3AA-22EH30	BMW 740i	2024	4
ZAA-32FK45	BMW i5 eDrive40	2024	9
ZAA-12HH45	BMW i5 eDrive40 Touring	2024	2
ZAA-32HH89	BMW i5 M60 xDrive Touring	2024	1
ZAA-42EJ49	BMW i7 eDrive50	2024	2
ZAA-82EH93	BMW i7 M70 xDrive	2024	1
		TOTAL	211