VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-4019	DATE	9 th June, 2025	
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)			
DESCRIPTION OF DEFECT	The affected vehicles are equipped with an active front stabilizer. The front stabilizer may have a manufacturing error. As a result, the front stabilizer could break over time. A broken anti-roll bar causes loud interference noises (e.g. hitting, rattling noise) as you continue driving.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-22CS44 -	BMW XM LABEL	2023-2024	7
	BMW XM	2023	48
		Total	55