

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-4015	DATE	June 12, 2025
MANUFACTURE	FCA US LLC (Japanese Importer : Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	The rear fog lamps may have an intermittent electrical connection. The molding process for the fog lamp electrical connector created connector cavities which were too large, leading to a loose connection between the fog lamp and the electrical harness.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-JL20L	「Wrangler Unlimited」	2024	310
7BA-JL20L	「Wrangler Unlimited」	2024	172
7BA-JL20S	「Wrangler」	2024	14
		TOTAL	496