

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4030	DATE	July 4, 2025
MANUFACTURE	Aston Martin Lagonda Limited (Japanese Importer : Aston Martin Japan Limited)		
DESCRIPTION OF DEFECT	Due to an improper manufacturing process, screws of varying lengths were used to secure the rear fuse box panel, resulting in contact with the electrical wiring. If the vehicle continues to be used in this condition, vibrations during driving could damage the wiring, potentially triggering a warning light and disrupting the vehicle's power supply. This could cause the engine to stall while driving and, in the worst-case scenario, result in a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NA	Valkyrie	2022-2024	6
		TOTAL	6