VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai–4042	DATE	July 17, 2025	
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : Stellantis Japan Ltd.)			
DESCRIPTION OF DEFECT	Some Peugeot 308 and 408 vehicles have been equipped with a Door Control Unit which has not the latest software version. This can potentially cause various malfunctions that prevent the front doors from opening or closing, the exterior mirrors from folding or adjusting, and/or the vehicle from moving forward (transmission locked in "P"). In the worst-case scenario, this may lead to window anti-pinch protection not working, which may result in a non-compliance with regulatory requirements.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3BA-P54HN05	Г408_	2023–2024	48
3LA-P545G06H	「408 HYBRID」	2024	31
3DA-P51YH01	Г308 ₋]	2024	1
3LA-P515G06H	「308 HYBRID」	2024	1
		TOTAL	81