

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-4055	DATE	2025/8/21
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan G.K.)		
DESCRIPTION OF DEFECT	On certain E-Class Saloon (213 platform) vehicles with 4-cylinder diesel engine, the software of the engine control unit might not meet specifications. In case of a malfunction of the mass air flow sensor or the low-pressure exhaust gas recirculation valve, the malfunction indicator lamp (MIL) could incorrectly not illuminate or illuminate delayed. In this case, local legal requirements might not be met.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-213004C	E220d	2016	1,095
		2017	1,473
		2018	3
LDA-213204C	E220d Stationwagon	2016	395
		2017	1,346
		2018	3
LDA-213217	E220d 4MATIC Stationwagon	2017	243
		2018	2
		TOTAL	4,560