

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ☒ Import Vehicles

CAMPAIGN No.	Gai-4058	DATE	2025/8/21
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan G.K.)		
DESCRIPTION OF DEFECT	On certain AMG ONE (298 platform) vehicles, locking pins on the hydraulic line of the rear spoiler might not be installed as required. In this case, hydraulic fluid could leak and subsequently come into contact with hot components of the exhaust system, which could increase the risk of fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	Mercedes-AMG ONE	2023	7
		TOTAL	7