

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 4049	DATE	5 August, 2025
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	For the snap ring to secure the top mounted cover of both right and left front air suspension struts, it could not slide completely into the recess, consequently, the top mounted cover is not secured properly due to inappropriate production process. Therefore, it is possible that air in the air spring is lost with the top mounted cover detached by vibration made by driving etc. and, in the worst case, handleability of the steering may be lowered because of unexpected change of vehicle height.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「3LA-G3SB」	Panamera 4 e-hybrid	2025	4
「3LA-G3SC」	Panamera 4S e-hybrid		3
「7BA-G3RA1」	Panamera		8
「7BA-G3RA2」	Panamera 4		1
「7BA-G3SD」	Panamera GTS		4
		Total	20