VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI 4051	DATE	2025. 8. 1	
MANUFACTURE	SCANIA CV AB			
	(Japanese Importer: SCANIA JAPANA Co. Ltd.)			
DESCRIPTION OF DEFECT	In the front light unit, due to insufficient design study, the internal components may deteriorate faster than usual due to the effects of heat generated by the LED structure itself. This may cause the internal components to suffer heat loss through continuous use, resulting in a decrease in the illuminance of the daytime running light and width light and a change in the color of the light.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	LPGRS series Truck	2020-2024	49
		TOTAL 2020-2024	49