

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

|                       |                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |      |          |
|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|----------|
| CAMPAIGN No.          | GAI－4063                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | DATE | 2025/9/5 |
| MANUFACTURER          | Fendt<br>(Japanese Importer :MSK Farm Machinery Corporation<br>CEO Takahata Toshinobu)                                                                                                                                                                                                                                                                                                                                                                                       |      |          |
| DESCRIPTION OF DEFECT | On the engines of agricultural tractors, engine oil leakage may occur due to deterioration of the oil because the material of the oil filter cap is incorrect if the engine oil is not changed according to the operator manual.<br>Therefore, if the engine is used continuously, lubrication of the engine may be insufficient, and the engine may stop in the worst case.<br>We will replace the cap of the oil filter with a non-defective one on all affected vehicles. |      |          |

|      |                 |                     |                   |
|------|-----------------|---------------------|-------------------|
| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
| 不明   | F1050VARIO S4   | 2017-2019           | 3                 |
|      |                 | TOTAL               | 3                 |