

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIN No.	Gai – 4103	DATE	30 Oct, 2025
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to an inappropriate manufacturing process, right-hand drive vehicles have airbag control unit software that is programmed to identify door pressure sensors for left-hand drive specifications. As a result, the driver's and passenger's side airbag signals may not be processed properly in the event of a side impact, which may result in the airbags not deploying as intended, and in the worst case scenario, may result in injury to the occupants.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-G3RA1	Panamera	2025~2026	538
7BA-G3RA2	Panamera 4		216
7BA-G3SD	Panamera GTS		189
7BA-G3TD	Panamera GTS		41
3LA-G3SB	Panamera 4 e-hybrid		159
3LA-G3SC	Panamera 4S e-hybrid		60
3LA-G3SE	Panamera Turbo		44
3LA-G3SF	Panamera Turbo S		35
		Total	1,282