

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI 4077	DATE	October 7, 2025
MANUFACTURE	SCANIA CV AB (Japanese Importer: Millerjapan Co. Ltd.)		
DESCRIPTION OF DEFECT	In the front light unit, due to insufficient design study, the internal components may deteriorate faster than usual due to the effects of heat generated by the LED structure itself. This may cause the internal components to suffer heat loss through continuous use, resulting in a decrease in the illuminance of the daytime running light and width light and a change in the color of the light.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	Scania (LPGRS series Truck)	2021	1
		TOTAL	1