

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-4135	DATE	December 24, 2025
MANUFACTURE	Rosenbauer International AG (Japanese Importer : TEIKOKU SEN-I Co.,Ltd. )		
DESCRIPTION OF DEFECT	In the planetary gear pins, which are components of the hub reduction mechanism, may have insufficient strength due to improper manufacturing processes. As a result, during use, the planetary gear pins may wear out, and in the worst-case scenario, break and jam the gears, potentially making the vehicle inoperable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ROSENBAUER	Panther	2025	6
ROSENBAUER	Pantehr HRET	2025	1
	TOTAL		7