

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-4118	DATE	04/12/2025
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Volvo has identified that vehicles exposed to hot climate conditions over time can cause the doorlatch to weaken and the retention hook for the pawl spring in the side door latch to break. This can make the doors difficult to latch, or lead the driver/passenger to believe the door is securely closed when it is not.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[Volvo S60]	2011-2017	6, 436
VOLVO	[Volvo V60]	2011-2017	14, 789
VOLVO	[Volvo V60CC]	2016-2017	1, 342
		TOTAL	22, 567