

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-4138	DATE	28 th Jan, 2026
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	During sub-supplier's production process, the torsion bars of the front seat belt retractors were mechanically damaged due to a maintenance intervention. This may lead to a failure of the torsion bars during an accident. In this case the seat belt will unroll uncontrollably and would lose its function which impairs the restraining effect.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-42EG20T	BMW X1 xDrive20d	2025	1
		Total	1