

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	外-4140	DATE	January 23, 2026
MANUFACTURER	AGCO S.A.S. (Japanese Importer: ISEKI & CO., LTD.)		
DESCRIPTION OF DEFECT	In the protective cover for the 4WD shaft of the agricultural tractor, the strength of its mounting portion is insufficient due to inadequate design considerations. Continued operation in this condition may cause the mounting portion to crack and fracture, and in the worst case, the cover may detach from the vehicle and pose a hazard to other road users.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	T5S145	2023 ~ 2024	5
-	T5S135	2023 ~ 2024	5
-	T5S115	2024	1
		TOTAL	11