

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI-4150	DATE	March 10, 2026
MANUFACTURE	SCANIA CV AB (Japanese Importer: SCANIA JAPAN Co. Ltd.)		
DESCRIPTION OF DEFECT	<p>Due to insufficient design consideration in the engine control unit, the hydraulic control valve inside the high-pressure fuel pump may become stuck after extended driving distances.</p> <p>As a result, the fuel injection quantity may become insufficient, leading to unstable engine output, clutch slippage, and in the worst case, the engine may fail to restart.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	LPGRS series Truck	2024-2025	3
		TOTAL	3