

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4180	Date	April 28, 2026
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the control unit of the electric power steering, the design of the control program is insufficient, so when the internal parts of the electric power steering motor are in a high temperature state, the abnormal detection system may detect the mechanical vibration of the motor as a fault state. Therefore, when the warning light is turned on, the steering assist function is disabled, and the steering operation power may increase.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-CDDXD	Golf 1.5 TSI	2026	1,005
7BA-CDDNP	Golf GTI	2026	151
3DA-CDDTT	Golf TDI/110kW	2026	208
7BA-CDDNFF	Golf R 2.0/245kW	2026	135
3AA-CDDXDV	Golf Variant 1.5 TSI	2026	380
3DA-CDDTSV	Golf Variant TDI/110kW	2026	117
7BA-CDDNFV	Golf R Variant	2026	27
3AA-CJ15V	Passat 1.5 TSI	2026	183
3LA-CJ15V	Passat GTE	2026	55
3DA-CJ20V	Passat 2.0 TDI	2026	132
3AA-CT15	Tiguan 1.5 TSI	2026	488
3DA-CT20	Tiguan 2.0 TDI	2026	235
		Total	3,116