

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4184	DATE	28th Apr 2026
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K. )		
DESCRIPTION OF DEFECT	The connection system may suffer significant damage and may not function, resulting in decreased alternator performance, thereby increasing the risk of an injury. In extreme cases, there have been reports of smoke and signs of overheating, including scorched connectors and thermal damage to surrounding components.		

2BL-DGJ900	Bonville T100	2021 - 2022	252
	Street Twin	2020 - 2022	232
	Street Scrambler	2021 - 2022	267
2BL-DHJ1200	Bonneville T120	2020 - 2021	1
8BL-DGJ900	Bonville T100	2022 - 2023	387
	Speed Twin 900	2022 - 2023	862
	Scrambler 900	2022 - 2023	285
8BL-DHJ1200	Bonneville T120	2021- 2023	1467
		TOTAL	3,753