

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4172	Date	April 17, 2026
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the control unit of the electric power steering, the design of the control program is insufficient, so when the internal parts of the electric power steering motor are in a high temperature state, the abnormal detection system may detect the mechanical vibration of the motor as a fault state. Therefore, when the warning light is turned on, the steering assist function is disabled, and the steering operation power may increase.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-CDDXD	Golf 1.5 TSI	2025	3,706
7BA-CDDNP	Golf GTI	2025	962
3DA-CDDTT	Golf TDI/110kW	2025	1,956
7BA-CDDNFF	Golf R 2.0/245kW	2025	882
3AA-CDDXDV	Golf Variant 1.5 TSI	2025	1,744
3DA-CDDTSV	Golf Variant TDI/110kW	2025	1,324
7BA-CDDNFV	Golf R Variant	2025	594
3AA-CJ15V	Passat 1.5 TSI	2025	836
3LA-CJ15V	Passat GTE	2025	321
3DA-CJ20V	Passat 2.0 TDI	2025	363
3AA-CT15	Tiguan 1.5 TSI	2025	1,947
3DA-CT20	Tiguan 2.0 TDI	2025	1,086
		Total	15,721