

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5300	DATE	April 11th, 2023
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	With the engines (Engine model: 1ZS and 1KD) of diesel engine forklift and shovel loader vehicles, there are cases where amount of PM (Particulate Matter) included in emission gas exceeds regulation values. Due to improper program of engine control unit, in case of long-hour usage, there is a possibility that injector becomes deteriorated and leads to exhaust PM more than the regulation values.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-A8FDL18	TOYOTA GENE0	2014 - 2023	2,090
YDN-A8FDL25		2014 - 2023	8,628
YDN-A8FDL30		2014 - 2023	954
YDN-A8FD18		2014 - 2023	6,426
YDN-A8FD25		2014 - 2023	26,309
YDN-A8FDJ35		2014 - 2023	16,589
YDN-8FD40		2014 - 2023	5,675
YDN-8FD50		2014 - 2023	3,573
YDN-8FD80		2014 - 2023	1,518
YDN-A6SD7		TOYOTA Excavator Loader	2014 - 2023
YDN-A6SD12	2014 - 2023		326
YDN-A6SD15	2014 - 2023		217
		TOTAL	72,366