

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5347	DATE	June. 29. 2023
MANUFACTURER	Kawasaki Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>On certain eligible units, during the front wheel assembly process, the tightening torque of the certain bolts and nuts might be insufficient. As a result, the bolts and nuts may become loose, which can cause abnormal noise, reduced running stability, reduced braking force, and similar issues.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
8BL-EL400A	ELIMINATOR ELIMINATOR SE	2024	208	
		TOTAL	208	