

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5348	D A T E	July.13. 2023
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	In the vehicle manufacturing process, the equipment setting for the electrical component check process was improper, resulting in a failure to check the readability of software information for certain electrical component.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-GU6	「IMPREZA」	2023	67
3BA-GU7		2023	77
		TOTAL	144