

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5370	DATE	Aug. 31. 2023
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	In some of the vehicles/trucks equipped with the headlight manual leveling system, the headlight aiming measurement/adjustment may have been performed with the improper position setting of the headlight leveling switch. As the result, the headlight optical axis aiming may not comply with the safety regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
3BD-DA16T	CARRY	2022	1	
5BD-DA17V	EVERY		1	
5BD-DR17V	NV100 CLIPPER	2023	1	
5BD-DG17V	SCRUM		1	
		TOTAL	4	