

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5374	DATE	Aug 31, 2023
MANUFACTURER	AZAPA		
DESCRIPTION OF DEFECT	In vehicles converted to electric vehicles, the connector of the high-voltage harness of the DCDC converter and Onboard charger integrated unit is not waterproof, and water may enter the connector when driving in the rain. If the vehicle continues to be used as it is, the insulation of the high-voltage section will deteriorate, and the fail function may cut off the power supply, rendering the vehicle inoperable or making it impossible to charge the battery.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-LA350S	Mira e:s	2023	7
TOTAL			7