VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	5375	DATE	September 19. 2023	
MANUFACTURE	Topre Corporation			
DESCRIPTION OF DEFECT	In the heating system of a refrigerated freezer vehicles that uses engine cooling coolant as a heating medium, due to insufficient confirmation during design, there are vehicles that the initial setting of the clearance between the coolant piping and the back of the cabin is insufficient in the engine room. Therefore, as the vehicle ages, the coolant piping and the back of the cabin repeatedly interfere with each other, potentially damaging the piping and causing coolant to leak. If continue to use the vehicle in this state, a warning message and/or buzzer will sound indicating that the vehicle's cooling water level is low.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-NPR88AN	ELF	2018~2022	8
2PG-NPR88YN		2018~2021	11
2PG-NPS88AN		2019~2022	38
2RG-NPR88AN		2019~2022	1548
2RG-NPR88YN		2019~2022	4
2RG-NPS88AN		2020	2
2SG-NPR88AN		2019~2022	339
		TOTAL	1,950