

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5391	DATE	Oct. 18. 2023
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>On certain mechanical automatic transmission control computers of light duty hybrid trucks, due to inappropriate settings for the control program and motor replacement time for the automatic clutch activation motor, if the motor is close to its life limit,</p> <p>① It takes a long time to check the motor and the motor is mistakenly detected as a defect and the clutch operation is stopped, possibly causing the warning light to be illuminated and the vehicle unable to move.</p> <p>② In case the vehicle is parked with the gear put in, the clutch may not be disengaged when trying to start the engine, possibly causing the engine to not start.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
SJG-XKC605M	[Hino Dutro]	2011~2023	654	①654
2SG-XKC605M				②58
SJG-XKC605M				
TQG-XKC605M				
TSG-XKC605M				
SJG-XKC645M		2011~2019	139	①139
TQG-XKC645M				②32
TSG-XKC645M				
SJG-XKC655M		2011~2019	151	①151
TQG-XKC655M				②36
TSG-XKC655M				
SJG-XKU600M		2011~2019	918	①918
SJG-XKU600X				②88
TQG-XKU600M				
TQG-XKU600X				
TSG-XKU600M				
2SG-XKU605M		2011~2023	495	①495
2SG-XKU605X				②25
SJG-XKU605M				
TQG-XKU605M				
TSG-XKU605M				
SJG-XKU640M		2011~2018	67	①67
TQG-XKU640M				②6
TSG-XKU640M				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
2SG-XKU645M	[Hino Dutro]	2011~2021	63	①63
SJG-XKU645M				②3
TQG-XKU645M				
TSG-XKU645M				
SJG-XKU650M		2011~2019	275	①275
TQG-XKU650M				②47
TSG-XKU650M				
2SG-XKU655M		2011~2023	389	①389
SJG-XKU655M				②21
TQG-XKU655M				
TSG-XKU655M				
SJG-XKU700M		2011~2017	227	①227
TQG-XKU700M				②8
TSG-XKU700M				
2SG-XKU702M		2017~2022	67	①67
TSG-XKU702M				②24
2SG-XKU710M		2011~2022	1,866	①1,866
SJG-XKU710M				②105
SQG-XKU710M				
TQG-XKU710M				
TSG-XKU710M				
2SG-XKU712M	2017~2023	888	①888	
TSG-XKU712M			②213	
2SG-XKU720M	2011~2022	497	①497	
SJG-XKU720M			②15	
TQG-XKU720M				
TSG-XKU720M				
2SG-XKU722M	2017~2023	91	①91	
TSG-XKU722M			②26	
SJG-XKC605	[Toyota Dyna 200]	2011~2022	455	①455
2SG-XKC605	[Toyota Dyna 300]			②31
SJG-XKC605	[Toyota Dyna 400]	2011~2022	455	
TQG-XKC605	[Toyota Toyoace G25]			
TSG-XKC605	[Toyota Toyoace G35]			
TSG-XKC645	[Toyota Toyoace G45]	2018	1	①1②1
SJG-XKC655	[Toyota Dyna 200]	2011~2019	13	①13
TQG-XKC655				②0
TSG-XKC655				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
SJG-XKU600	[Toyota Dyna 200]	2011~2019	45	①45
SJG-XKU600A	[Toyota Dyna 300]			②5
TQG-XKU600	[Toyota Dyna 400]			
TQG-XKU600A	[Toyota Toyoace G25]			
TSG-XKU600	[Toyota Toyoace G35]			
TSG-XKU600A	[Toyota Toyoace G45]			
2SG-XKU605		2011~2022	150	①150
SJG-XKU605				②12
TQG-XKU605				
TSG-XKU605				
SJG-XKU640		2011~2016	4	①4
TSG-XKU640				②0
2SG-XKU645		2011~2019	2	①2
SJG-XKU645				②0
SJG-XKU650		2011~2019	428	①428
TQG-XKU650				②98
TSG-XKU650				
2SG-XKU655		2011~2022	64	①64
SJG-XKU655				②10
TQG-XKU655				
TSG-XKU655				
SJG-XKU700		2011~2018	51	①51
TQG-XKU700				②9
TSG-XKU700				
2SG-XKU702		2018~2020	10	①10
TSG-XKU702				②1
2SG-XKU710		2011~2022	174	①174
SJG-XKU710				②21
TQG-XKU710				
TSG-XKU710				
2SG-XKU712		2018~2022	38	①38
TSG-XKU712				②11
SJG-XKU720		2011~2017	35	①35
TQG-XKU720				②16
TSG-XKU720				
2SG-XKU722		2018~2022	22	①22
TSG-XKU722				②7
		TOTAL	8,279	①8,279②929